





















HUS-H	 h_1	 h_1	t_{fix}
6 x 40	50 mm - t_{fix}	43 mm - t_{fix}	0 ... 5 mm
6 x 60	70 mm - t_{fix}	63 mm - t_{fix}	2 ... 25 mm
6 x 80	90 mm - t_{fix}	83 mm - t_{fix}	5 ... 45 mm
6 x 100	110 mm - t_{fix}	103 mm - t_{fix}	25 ... 45 mm
6 x 120	130 mm - t_{fix}	123 mm - t_{fix}	45 ... 85 mm





1.1			
			
d_0	$\varnothing 6 \text{ mm}$	$\varnothing 6 \text{ mm}$	$\varnothing 5 \text{ mm}$



3.1				h_{nom}				
				35 mm	55 mm	55 mm	55 mm	
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18 Nm	25 Nm	12 Nm	6 Nm
	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				
	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>				





HUS-H	 h ₁	t _{fix}
6 x 40	43 mm - t _{fix}	0 ... 5 mm
6 x 60	63 mm - t _{fix}	2 ... 25 mm
6 x 80	83 mm - t _{fix}	5 ... 45 mm
6 x 100	103 mm - t _{fix}	25 ... 65 mm
6 x 120	123 mm - t _{fix}	45 ... 85 mm

